

READ ME FILE

LITEON IT 2002/11

The purpose of this READ ME file is to help you to install the external CD-RW drive under Windows98 step-by-step. You can find the driver for the USB adapter cable either in the included Floppy Disc or in the USB Adapter Cable directory of the CD kit.

Cautions before installation:

1. This driver is for Windows98 only, Windows ME/2000/XP do not require any drivers, as they will install the USB Adapter Cable's driver automatically
2. Please make sure the USB device is functioning normally, and there is no other an unknown device or hardware problems.

Step-by-step installation:

1. Make sure the cables (power cable & USB Adapter cable) are properly connected to the CD-RW Drive
2. Connect the USB Adapter cable to your computer
3. Start your computer
4. While Windows98 is booting up, it will ask to provide the driver for the new device, which it has detected. Please insert the Floppy Disc and direct the route to your floppy drive (A:\) or your CD drive's subdirectory (\usb adapter cable)
5. When the driver's installation has completed, it will ask to place the Windows 98 source disk
6. Restart your computer, when all installations have been complete
7. Check if you can see the CD-RW drive under " My Computer "