

ZyXEL GS1900-24E V2.00(AAHK.1)C0

Release Note

Date: Nov 26, 2014

This document describes the features in the GS1900-24E product for its 2.00(AAHK.1)C0 release.

Support Platforms:

ZyXEL GS1900-24E V2.00(AAHK.1)C0 supports models: ZyXEL GS1900-24E

Version:

OS Version: V2.00(AAHK.1) | 10/20/2014

BootBase Version: V1.00 | 1/16/2014

Default Bootbase Setting:

ZyNOS Version	V2.00(AAHK.1) 10/20/2014
Bootbase Version	V1.00 1/16/2014
Vendor Name	ZyXEL
Product Model	GS1900-24E
ZyNOS Code Model	GS1900-24E

Bug Fix:

1. [General] After rebooted, unable to save the password which is encrypted with 15 characters
 2. [WebGUI] When configure IPv6 DNS, it will cause display wrong MGNT vlan, and multiple DNS IPv6 address.
 3. [WebGUI] Fix PoE power budget amount display with a wrong value
-

4. [WebGUI] Fix mac-address range incomplete display.
5. [WebUI] System Name can't set space string
6. [Interface] GS1900 series can't set port speed to 1000M via Web

Enhanced Features:

Known Issue:

-
1. [WebUI] Login page's system name characters will over the border when system name is set to 64 characters.
 2. [Logging] If user tries to restore an illegal configuration (unofficial), login will always show authentication fail.

Limitation of Settings:

-
1. 802.1s instances : 16
 2. Guest VLAN : 1
 3. Static MAC entries : 64
 4. The BWM works well with UDP only.

Change History:

V2.00(AAHK.1) | 10/20/2014
V2.00(AAHK.0) | 6/27/2014
V1.00(AAHK.0) | 7/16/2013
First Public Version

ZyXEL GS1900-24E V2.00(AAHK.0)C0

Release Note

Date: July 10, 2014

This document describes the features in the GS1900-24E product for its 2.00(AAHK.0)C0 release.

Support Platforms:

ZyXEL GS1900-24E V2.00(AAHK.0)C0 supports models: ZyXEL GS1900-24E

Version:

OS Version: V2.00(AAHK.0) | 6/27/2014

BootBase Version: V1.00 | 1/16/2014

Default Bootbase Setting:

ZyNOS Version	V2.00(AAHK.0) 6/27/2014
Bootbase Version	V1.00 1/16/2014
Vendor Name	ZyXEL
Product Model	GS1900-24E
ZyNOS Code Model	GS1900-24E

Bug Fix:

1. [Function] Jumbo Frame can't be forwarded.
2. [WebUI] Web GUI session timeout does not work correctly.
3. [IGMP Snooping] Multicast group traffic to stop forwarding by the switch if the switch keeps receiving join/leave message from its port(s).

4. [Mirror] Mirror function can not be configured via Web.
5. [SNMP] Fixed SNMP System description value(was empty).
6. [Config] Configuration can not be backup/restored in some browser.

Enhanced Features:

Support ZyXEL One Network utility

Known Issue:

-
3. [WebUI] Login page's system name characters will over the border when system name is set to 64 characters.
 4. [Logging] If user tries to restore an illegal configuration (unofficial), login will always show authentication fail.

Limitation of Settings:

-
5. 802.1s instances : 16
 6. Guest VLAN : 1
 7. Static MAC entries : 64
 8. The BWM works well with UDP only.

Change History:

V2.00(AAHK.0) | 6/27/2014

V1.00(AAHK.0) | 7/16/2013

First Public Version

ZyXEL GS1900-24E V1.00(AAHK.0)C0

Release Note

Date: July 18, 2013

This document describes the features in the GS1900-24E product for its 1.00(AAHK.0)C0 release.

Support Platforms:

ZyXEL GS1900-24E V1.00(AAHK.0)C0 supports models: ZyXEL GS1900-24E

Version:

OS Version: V1.00(AAHK.0) | 7/16/2013

BootBase Version: V1.00 | 7/16/2013

Default Bootbase Setting:

ZyNOS Version	V1.00(AAHK.0) 7/16/2013
Bootbase Version	V1.00 7/16/2013
Vendor Name	ZyXEL
Product Model	GS1900-24E
ZyNOS Code Model	GS1900-24E

Bug Fix:

None

Enhanced Features:

None

Known Issue:

-
1. [Flow Control] Flow control can't work under the force mode.

Limitation of Settings:

-
1. 802.1s instances : 16
 2. Guest VLAN : 1
 3. Static MAC entries : 64

Change History:

V1.00(AAHK.0) | 7/16/2013

First Public Version